

Huerfano River Point of Diversion Risk Summary

Structure or Point of Diversion ID	P(Score) Higher Score=Higher Risk	Likelihood of Damage from Post Fire Flooding
BADITO & MARTIN DITCH 1	2.7	Higher
BADITO & MARTIN DITCH 2	2.7	Higher
BAXTER PIONEER DITCH	0.8	Lower
BO BOYCE DITCH	0.4	Lower
BURNS DITCH NO 2	0.4	Lower
BUTTE VALLEY DITCH	0.4	Lower
CHAVEZ DITCH	0.4	Lower
DAN MAHAN DITCH	3	Higher
DEUS PIONEER DITCH	0.4	Lower
GARCIA DITCH NO 1	0.4	Lower
GARCIA DITCH NO 2	0.4	Lower
HAMLET DITCH	0.4	Lower
JACK ALLEN DITCH	3	Higher
JOHN W BROWN DITCH	1.8	Lower
JOSE MARIA DITCH	3	Higher
M & R DITCH (MEDINA NO3)	2.7	Higher
MARTIN DITCH	1.4	Lower
MARTINEZ DITCH	3	Higher
MAY DITCH	0.4	Lower
MEDINA FELIPA DITCH	2.7	Higher
MOLLA DITCH	0.4	Lower
ORLANDO CANAL NO 3	0.4	Lower
P P GONZALES DITCH	0.4	Lower
PEDRO GOMEZ DITCH	0.4	Lower
R L SMITH DITCH NO 1	0.4	Lower
RAHN & MARTINE DITCH	2	Middle
RAHN DITCH (MEDINA NO2)	0.4	Lower
ROY DITCH	0.4	Lower
S V GONZALES NO 1	0.4	Lower
S V GONZALES NO 2	0.4	Lower
S V GONZALES SEEPAGE	0.4	Lower
S&P DITCH	2	Middle
SANCHEZ DITCH	1.4	Lower
SOUTH SIDE DITCH	0.4	Lower
SPEED PROFFITT DITCH	0.4	Lower
UPPER HUERFANO NO 2	0.4	Lower
UPPER HUERFANO NO 3	0.4	Lower
VIGIL & CHAVEZ DITCH	0.4	Lower
WILLIAM CRAIG DITCH	3	Higher
WILSON DITCH	0.4	Lower
BURNS (PALO DURO) DITCH	0.4	Lower
MADRID DITCH	0.4	Lower
MESES Y COMPANY DITCH	0.4	Lower
CALDWELL IRRIGATING	1.8	Lower
DEUS PASS CREEK DITCH	0.4	Lower
EPIFANIO DITCH	2.4	Middle
FRANCISCO MESTES DITCH	2.4	Middle
GARDEN DITCH (PASS CRK)	0.4	Lower
GIMLET DITCH	0.8	Lower
LEWIS DITCH	1.8	Lower
LEWIS DITCH AUG STATION	1.8	Lower
MARQUES DITCH	0.4	Lower
SPRING IRRIGATING DITCH	0.4	Lower